

Protmex Digital Temperature Humidity Meter

1. Press the green Power button to turn the device on.
2. Press the C/F button to select temperatures to be displayed in either Celsius or Fahrenheit. A C or F will be shown in the bottom right corner of the screen.
3. For dewpoint measurements, press the DP WB button once (Dew Point will be shown on the left side of the screen). For wet bulb measurements, press the DP WB a second time (Wet Bulb will be shown on the left side of the screen). To switch back to the ambient temperature, press the DP WB a third time.
4. To freeze the screen, press the purple H button. HOLD will be displayed at the top left of the screen. To unfreeze, press the purple H button again.
5. The yellow light button will light up the screen.
6. Press the green Power button to turn the device off.



Tips for Use

- This device's measurement considers sun cover, humidity and winds so it will vary across the venue based on the topography.
- Humidity readings can be impacted by presence of water, such as watering of the ring or a pond or fountain. However, measurements with misting fans can be used to suppress effectiveness of mitigation.
- Multiple readings should be taken, with the overall average measurement being the one that is considered.
- The sensors are on the top of the device. Hold the device away from your body, with the device facing up towards the sky.
- Avoid holding the device flat or toward the ground as this will affect the measurements.